


Company Model	Drawing	No.	Spare part	Quantity	Material	size	L	H	DN	PN	WEIGHT
S8088		1	bonnet	1	brass	F1/2**1216				1.6MPa	46
		2	adapter	1	brass						
		3	cut sleeve	1	brass						
		4	O-ring	2	EDPM						
		5	O-ring	2	EDPM						
		6	gasket	1	PTFE						
							thread according to ISO228				
						Working Temperature: -20°C≤t≤+110°C					